

## 2701 : Voltage meter



For measuring voltage and continuity. Operating and battery test. 6 to 600 V - ac or dc. Operates with a 12 V alkaline battery. Battery included.

KG	REF
0,150	270110